

## **N3074 Firmware Release Notes**

**Version: V1.09.2\_STD-1**

**Release Date: 2014/07/16**

---

---

**Added:**

1. Add support for IE 11.
2. Add GOP value 3 for video codec setting.
3. Add Date Format selection for OSD setting (YYYY/MM/DD, MM/DD/YYYY, DD/MM/YYYY).

**Fixed:**

1. Fix Tour bug which will waiting extra time for each empty preset setting.
2. Fix Alarm output duration bug with Milestone using ONVIF.
3. Fix RTSP pause command issue which may cause streaming disconnect.
4. Fix flicker setting to 50 for PAL.

**Update:**

1. Update ActiveX to fix Snapshot crash issue.
2. Update ActiveX which will prevent Focus Assist value lost when using digital Zoom.

**Version: V1.08 STD-1**

**Release Date: 2013/11/14**

---

---

※In order to enhance better compatibility with 3S camera. Please upgrade the **Camfinder** to version **1.5** after updating this camera firmware

**Camfinder V1.5** download link: <https://www.dropbox.com/s/h5i0iaryz89j32i/camfinder.rar?m=>

**Added:**

1. ONVIF Profile S Support
2. IE 10 Support
3. Add camera log messages when using CamFinder to update network setting.
4. Add SNMP protocol.

**Fixed:**

1. Fix "number of current viewers" bug of abnormal counting in IE10
2. Fix Recording List bug of file missing for some condition.
3. Fix Time Zone bug which some Time Zone options are invalid
4. No images on the page of motion detection when using DDNS function.
5. Fix the bug of error message pop up on the live view page when adjusting the image brightness
6. Fix the detection bug in IE10, which there is no flickering for detected line or area when the event is triggered
7. The fixed IP will be changed to DHCP after updating the firmware.

**Modified:**

1. Update ActiveX to 1.2.5
2. Pelco-P & Pelco-D ptz driver updated for some PTZ Dome
3. Improve SD Card recording function which may stop working for some condition
4. Multicast performance improved

**Known bug:**

1. Not support IE11 yet
2. IE will be crash when using Alarm Snapshot function in live view page

**Version: V1.06 STD-1**

**Release Date: 2013/03/27**

---

---

※ Suggest to update the firmware in LAN environment. Otherwise, the current IP address may go back to default(192.168.0.20).

**Fix:**

- Fix ONVIF setting bug for Milestone
- Fix UDP connection bug for some third party software which may disconnect in 20 seconds due to no rtcp reply
- Fix SD card recording issue which may stop recording
- Fix some translation bugs for web page

**Version: V1.04 STD-1**

**Release Date: 2012/06/21**

---

---

**Add:**

- Support ONVIF 1.02.4.3 Test tools.
- Add Traditional Chinese for OSD setting.

**Modified:**

- Update Motion Detection and Tamper Detection setting page which can show a blink window when specified window event been triggered.

**Fixed:**

- Fix critical camera bug which will usually lead to disconnect when using for a period of time.
- Fix Recording List bug which SD card cannot correctly playback in specified file.
- Fix camera ftp server bug which cannot connect SD card in unusual situation or some settings.
- Fix some improper language translation (Especially for France).
- Fix bug which system will reboot if streaming reconnect very often.
- Fix bug for ONVIF which cannot search by iNEX.
- Fix Live View bug which video will disappear if click on ActiveX when page loading.
- Fix default FPS error for Milestone with ONVIF.

**Version: V1.03 STD-1**

**Release Date: 2011/11/11**

---

**Modified:**

- Change default value for Motion Detection which will be enabled when startup

**Fixed:**

- Fix ONVIF bug which will reboot when DHCP failed
- Fix RTSP auth issue which will reject some softwares  
rtsp connections
- Fix Alarm bug which will failed sometimes (ex: Reset to Default)